

Stormwater BMP Owner Inspection Form Infiltration Basin City of Columbia, Missouri

Addres	s: ₋						
Owner:	_						
Legal:	_						
Date:		E-mail:			Phone: ()		
I. GEN	IER/	AL INSPECTION RES	ULTS	3			
Item		Inspection Results			BMP's in General		
1		Apparent problems		No problems	BMP does not appear to be well maintained.		
2		Design flaws		No flaws	BMP observed to have significant design flaws which lessen its effectiveness.		
3		Unauthorized modifications		No modifications	BMP has unauthorized modifications that reduce its effectiveness.		
4		BMP removed		BMP present	BMP has been destroyed or removed from property.		
5		Trash		No Trash	Trash and debris has accumulated on/in BMP. Yard waste in BMP.		
6		Contaminated		Uncontaminated	Evidence of Oil, gasoline. Contaminants or other pollutants.		
7		Smells		Doesn't smell	Unpleasant odors from the BMP.		
II. BM	P SF	PECIFIC INSPECTION	RES	BULTS - INFILTRAT	TION BASIN		
Item		Inspection Results		BMP : Infiltration Basin			
1		Clogged		Not clogged	Flow spreader uneven or clogged so flows are not uniformly distributed across BMP.		
2		No sediment trapped		Sediment trapped	The forebay is not trapping sediment before it reaches infiltration basin.		
3		Silted in		Enough capacity	Capacity in sediment forebay is less than 50% of design capacity.		



Stormwater BMP Owner Inspection Form Infiltration Basin

Stormwater Utility City of Columbia, Missouri

4	Inlets need repair	Inlets in good condition	Inlets/pipes are crushed, deformed, damaged, corroded, and in need of repair.	
5	Flow bypasses facility	Flow enters BMP	Flow bypasses facility by overtopping berms, erosion channels, or other means.	
6	Weeds	No weeds	Invasive, nuisance vegetation or weeds are present.	
7	Brush/trees	Proper vegetation	Growth of brush and trees does not allow for proper maintenance. Dead, diseased, or dying trees are present. Tree growth on berms or emergency spillway > 4' in height or covering more than 10% of spillway.	
8	Sediment accumulated	No accumulated sediment	Sediment in storage areas, rock filters, and pre-settling ponds and vaults prevents infiltration.	
9	Erosion	No erosion	Eroded damage over two inches deep; potential for continued erosion; any erosion on a compacted berm embankment; soil from adjacent areas washes into/on BMP; continued erosion is prevalent.	
10	Rodent holes	No rodent holes	If facility acts as a dam or berm, any evidence of rodent holes, or any evidence of water piping through dam or berm via rodent holes.	
11	Insects	No insects	Wasps, hornets or bees interfere with maintenance activities. Excessive or nuisance levels.	
12	Standing water	No standing water	Water is observed within the BMP (between storms) and appears not to drain freely or soil is excessively soggy. Excessive ponding of water within vegetated swale or other BMP.	



Stormwater BMP Owner Inspection Form Infiltration Basin City of Columbia, Missouri

1. Is maintenance needed at t	his time?	□ Yes	□ No								
2. Are mosquitoes or mosquito	o larvae present?	□ Yes	□ No								
3. Maintenance items needed/completed:											
Return completed form by either of the following:											
Email – stormwaterbmp@como.gov (preferred method)											
Mail – City of Columbia Stormwater Utility, P.O. Box 6015, Columbia, MO 65205-6015											
For questions, call (573) 441-5530.											
Inspected by:											
Signature											
											
[Print Full Name]											
FOR CITY USE ONLY - DO N	IOT FII I										
		eived									
Date received :	By:_										
Comments/Corrective actions required:											